

MINITOR VI Firmware upgrade Kit R01.09

Customer Release Notes

For any questions, please contact Customer Resources at 1-800-927-2744.

I. Enhancements

FW R01.09 addresses the very faint birdie frequencies at 151.1675MHz and 151.1775MHz that may be noticeable in very weak signal coverage conditions.

II. Corrections

None

III. Known Issues

None